


SEW


FIG 735 Stationery Bouble- Acting Cylinder, Using V-Balt


CHANDER 1° STROKE DO CLOSE - ACHING 140D System 0.27-1 70-32-91 TUN TRUBHT 409-093 SUB-ASSEABLY A-409-011 TORQUE ARM GUIDE A-409-008 TORQUE ARM 2207 NUT 1/4-28 2120 SETSCREW, HEX SOCKET 1/4-28 X 1/4 LG 2454 BUTTON D521 JAD 134D 2606 RETAINING RING B-407-095 SUB-ASSEMBLY POOCS4-1 CONTROL STEM-A-407-429 BUSHING (2-REQD) 2288 BEARING 407-405 MOMING FACE A-407-018 DECAL A-407-306 KEY 2578 PLASTIC PLUG 2458 GREASE—PLACE IN BORE OF SHATI. 2708 LOCTITE D SETSCREM, HEX SOCKET AT ASSEMBLY (SEE CHART) 407-196 SUB-ASSEMBLY C-407-403 --SHWFT A-407-001 FDGD FACE

:, :,


; ; ivy:








F16 10



F1611



=1612




FIG. 14
SPRING-ASSISTED VENTING

